

WAAS CH <b>93601</b> <b>W20A</b>	APP CRS <b>206°</b>	Rwy Idg <b>4410</b> TDZE <b>955</b> Apt Elev <b>957</b>
--	------------------------	---

**RNAV (GPS) RWY 20**  
DAYTON-WRIGHT BROTHERS (MGY)

RNP APCH: Inoperative table does not apply. When local altimeter setting not received, use James M Cox Dayton Intl altimeter setting and increase all DAs/MDAs 60 feet and Circling Cat C/D visibility ¼ SM. Rwy 20 helicopter visibility reduction below ¾ SM NA. VDP NA when using James M Cox Dayton Intl altimeter setting.	MALS 	MISSED APPROACH: Climb to 3100 direct SOVVO and hold.
--	----------	--

ASOS <b>118.375</b>	COLUMBUS APP CON <b>118.85 269.275</b>	CLNC DEL <b>119.4</b>	UNICOM <b>122.8 (CTAF) 0</b>
------------------------	---	--------------------------	---------------------------------

