

ILS or LOC RWY 36
WITTMAN RGNL (OSH)

MISSED APPROACH: Climb to 1300 then climbing right turn to 3000 on OSH R-111 to LEWKO INT/OSH 15 DME and hold.

[illegible]