

VOR RWY 28
ST MARYS MUNI (OYM)

MISSED APPROACH:
Climbing right turn to 3900
via SLT R-264 to EMPOR
INT/18.4 DME and hold.

Diagram illustrating a flight path with various waypoints and altitudes:

- Keating**: ELEV 1934, TDZE 1934. Altitude 3900 (16.7) at R-008.
- Waypoint 3300**: Altitude 3300 (9.9) at R-333.
- Waypoint 2640**: Altitude 2640 (8.5) at R-264. Includes a 1 min hold at 264° and a 084° turn.
- Waypoint 2350**: Altitude 2350 (18.4) at EMPOR INT SLT 18.4.
- Waypoint 2359**: Altitude 2359 (1978) at 1978.
- Waypoint 2705**: Altitude 2705.
- Waypoint 2725**: Altitude 2725.
- Waypoint 2455**: Altitude 2455.
- MSA**: MSA SLT 25 NM, Altitude 3900.
- Destination**: SLATE RUN, ELEV 113.9, ETG 113.9, Chan 86.

Diagram illustrating the holding pattern for MRL Rwy 10-28. The pattern is a one-minute holding pattern. The diagram shows the FAF (Final Approach Fix) and the MAP (Missed Approach Point). The holding pattern is a one-minute holding pattern. The diagram also shows the FAF (Final Approach Fix) and the MAP (Missed Approach Point).

ST MARYS MUNI (OYM)
VOR RWY 28