

WAAS

CH **82738**

W30A

APP CRS

308°

Rwy Idg

4652

TDZE

2706

Apt Elev

2706

RNAV (GPS) RWY 30

HETTINGER MUNI (HEI)

⚠

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -20°C (-4°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. Circling NA northeast of Rwy 12-30. Circling NA to Rwys 17 and 35.

MISSED APPROACH:

Climb to 6000 direct HAYNI and hold, continue climb-in-hold to 6000.

ASOS 119.925	MINNEAPOLIS CENTER 124.25 236.825	UNICOM 122.8 (CTAF)
------------------------	---	-------------------------------

MSA RW30 25 NM

4600

ELEV 2706 TDZE 2706

6000

HAYNI

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 25).

*LNAV only

*1.7 NM to RWY30

IBOXE

5 NM Holding Pattern

128°

308°

5000

GP 3.00°

TCH 40

CATEGORY	A	B	C	D
LPV DA	2956-1		250 (300-1)	
LNAV/VNAV DA	3233-1 $\frac{7}{8}$		527 (600-1 $\frac{7}{8}$)	
LNAV MDA	3260-1	554 (600-1)	3260-1 $\frac{5}{8}$	554 (600-1 $\frac{5}{8}$)
CIRCLING	3260-1	554 (600-1)	3260-1 $\frac{5}{8}$	3460-2 $\frac{1}{2}$ 554 (600-1 $\frac{5}{8}$) 754 (800-2 $\frac{1}{2}$)

HETTINGER, NORTH DAKOTA

Amtd 1 26MAY16

46°01'N-102°39'W

RNAV (GPS) RWY 30

HETTINGER MUNI (HEI)