

ILS or LOC RWY 35R
DENVER INTL (DEN)

DENVER INTL (DEN)



MISSED APPROACH: Climb to 5800 then climbing right turn to 10000 on heading 048° and on GLL VORTAC R-136 to CEDUK/GLL 16 DME and hold.

RADAR or GPS REQUIRED

DENVER
117.9 DEN
Chan 126

LOCALIZER 110.15
I-DPP
Chan 38 (Y)

MISSED APCH FIX
114.2 GLL
Chan 89

CEDUK
GLL 16

130°
31.5

RADAR or GPS REQUIRED

DENVER
9 DEN 126
Chan 126

LOCALIZER 110.15
I-DPP ::::
Chan 38 (Y)

MISSED
APCH
FIX

CEDUK —
GLL 16

114.2 GLL
R-136
Chan 89
114.7 DW
R-019
Chan 94

ASA DEN 25 NM

9200

ALTERNATE MISSED APCH FIX

117.9 DEN
R-056
126 WITNE
DEN 25.6

117.9 DEN
R-056
126 WITNE
DEN 25.6

DENVER INTL (DEN)
ILS or LOC RWY 35R