



ILS RWY 4L (SA CAT I & II)  
NEWARK LIBERTY INTL (EWR)

- MALSR

**MISSED APPROACH:** Climb to 620 then climbing right turn to 2500 on heading 060° and TEB VOR/DME R-205 to TEB VOR/DME and hold.



SA CATEGORY I & II ILS - SPECIAL AIRCREW  
& AIRCRAFT CERTIFICATION REQUIRED

