

**ILS RWY 28 (CAT II)**  
SYRACUSE HANCOCK INTL (SYR)

**MISSED APPROACH:** Climb to 1100 then climbing right turn to 3000 direct SYR VORTAC and hold, continue climb-in-hold to 3000.



CATEGORY II ILS - SPECIAL AIRCREW  
& AIRCRAFT CERTIFICATION REQUIRED

SYRACUSE HANCOCK INTL (SYR)  
ILS RWY 28 (CAT II)