



ILS or LOC RWY 36R
CHARLOTTE/DOUGLAS INTL (CLT)

MISSED APPROACH: Climb to 1320 then climbing right turn to 4000 on CLT VOR/DME R-093 to LOCAS INT/24.9 DME and hold.

CHARLOTTE
115.0 CLT 
Chan 97



RADAR REQUIRED

1320 4000

CLT R-093 LOCAS CLT 24.9

VGS and ILS glidepath not coincident (VGS Angle 3.00/TCH 74).

HEKAM I-BQC 17.9

JENDA I-BQC 14.8 RADAR

LANSR I-BQC 11.6 RADAR

CIKDU I-BQC 8.5 RADAR

HAYOU I-BQC 6.9 RADAR

I-BQC 2.5 *I-BQC 1.5

2500 3000 4000 5000 6000

GS 3.00° TCH 55

1 NM 4.4 NM 1.6 NM 3.2 NM 3.2 NM 3.2 NM

CATEGORY	A	B	C	D
S-ILS 36R	927/18 200 (200-1/2)			
S-LOC 36R	1120/24 393 (400-1/2)		1120/35 393 (400-1/2)	
CIRCLING	1380-1 632 (700-1)		1500-2 1/4 752 (800-2 1/4) 1500-2 1/2 752 (800-2 1/2)	

SE-2, 03 DEC 2020 to 31 DEC 2020