

ILS or LOC RWY 35L
CITY OF COLORADO SPRINGS MUNI (COS)

MALSR

MISSED APPROACH: Climb to 6700 then climbing right turn to 9000 on heading 047° and on BRK VOR/DME R-091 to ADANE INT/BRK 11.1 DME and hold.

ALTERNATE MISSED APCH FIX
112.5 BRK
R-145
Chan 72

ADANE BRK 11.1
R-091
271°
091°

BLACK FOREST 112.5 BRK
Chan 72

LOCALIZER 109.9 I-COS

MSA CO 25 NM
9100
15400
8100
251°
021°

LOM PETEY 407 CO

IAF PUEBLO 116.7 PUB
Chan 114

IAF DRAKE BRK 22.7
R-145

ELEV 6187 D TDZE 6075

HIRL Rwy 17R-35L and 17L-35R
REIL Rwy 13, 17R, 31 and 35R
6207A TDZ/CL Rwy 17L and 35R
MIRL Rwy 13-31

TWR 121

Procedure NA for arrivals on PUB VORTAC airway radials 267 CW 354.

Procedure NA for arrivals
on PUB VORTAC airway
radials 267 CW 354.

FAF to MAP 6 NM					
Knots	60	90	120	150	180
Min:Sec	6:00	4:00	3:00	2:24	2:00

MIDAY INT PUB <u>21.4</u>		PETEY CO LOM		6700 ↑	9000 hdg 047°	BRK R-091	ADANE △
8100 — 352° —		8028		VGS1 and ILS glidepath not coincident (VGS1 Angle 3.00/TCH 71).			
<u>8100</u>		8100					
GS 3.00° TCH 51		7.4 NM		6 NM			
CATEGORY		A		B		C	
S-ILS 35L *		6275/24		200 (100-½)		D	
S-LOC 35L		6540-1 553 (600-1)		6540-½ 465 (400-½)		6540/50 465 (400-1)	
CIRCLING		6740-1 553 (600-1)		6800-1 613 (700-1)		7260-3 1073 (1100-3)	

SW-1, 03 DEC 2020 to 31 DEC 2020