

ILS or LOC RWY 34R
DENVER INTL (DEN)

MISSED APPROACH: Climb to 5800 then climbing left turn to 10000 on heading 270° and on FQF VORTAC R-306 to HYGEN/FQF 37.9 DME/RADAR and hold.

[illegible][illegible]

SW-1, 03 DEC 2020 to 31 DEC 2020