


WAAS CH <b>99621</b> <b>W30B</b>	APP CRS <b>303°</b>	Rwy ldg <b>10818</b> TDZE <b>583</b> Apt Elev <b>618</b>
--	------------------------	--

RNAV (GPS) Y RWY 30L

ST LOUIS LAMBERT INTL (STL)

RNP APCH.				<div>MALSR</div> <div></div>	MISSED APPROACH: Climb to 3000 direct TUDNE and hold, continue climb-in-hold to 3000.	
<div><div><div><div></div></div><div>LNAV procedure NA during simultaneous operations. Use of FD or AP required during simultaneous operations. Simultaneous approach authorized with Rwy 29. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -18°C or above 54°C. For inop ALS, increase LNAV Cat C/D visibility to 1½ SM. # RVR 1800 authorized with use of FD or AP or HUD to DA.</div></div></div>						
<div>D-ATIS</div> <div>125.025</div> <div>379.925</div>	<div>ST. LOUIS APP CON</div> <div>132.125 360.6</div>	<div>ST. LOUIS TOWER</div> <div>118.5 257.7</div>	<div>GND CON</div> <div>121.9 348.6 (Inbound)</div> <div>121.65 377.175 (Outbound)</div> <div>118.925 227.125 (Rwy 11/29)</div>	<div>CLNC DEL</div> <div>119.5 363.1</div>	<div>CPDLC</div>	

