

TAMPA, FLORIDA

ILS or LOC RWY 5

LOC I-MCF  
**109.5**

APCH CRS  
**044°**

Rwy ldg **11,421**  
TDZE **10**  
Arpt Elev **14**

AL-418 [USAF]

MACDILL AFB (KMCF)

RADAR or DME required.

\*When ALS inop, increase RVR to 40, vis to ¾ mile.

\*\*When ALS inop, increase CAT AB RVR to 55, vis to 1 mile; CAT CDE RVR to 60, vis to 1½ miles.

ALSF-1

† MISSED APPROACH: Climb to 2700 via MCF TACAN R-075 to MCF 22 DME and hold. Cross 8 DME at 1700.

ATIS  
**133.825 270.1**

TAMPA APP CON  
**124.95 354.0**

MACDILL TOWER  
**120.175 294.7**

GND CON  
**118.575 275.8**

\*\*\*Circling not authorized NW of Rwy 5-23.

† RNAV or ATC RADAR required for missed approach.

CAUTION:  
LOC course offset 2.86° from the extended rwy centerline and intersects the rwy centerline 1834' after the DA.

WARNING: Use extreme caution PETER O. KNIGHT airport 4 NM Northeast of MACDILL AFB.

ELEV	14	TDZE	10
------	----	------	----

EMERG SAFE ALT 100 NM 3000	1700 MCF R-075	2700 MCF
MILNE R-224 15	EMASE MCF 6.6 RADAR	MCF R-075 8
1600 224° 044° 1600	1600 044°	2700 044°
GS 3.00° TCH 55	4.3 NM	5

†† LOC only

†† 2.9

EMIME 2.3

TACAN

CATEGORY	A	B	C	D	E
S-ILS 5 *	260/24 250 (300-½)				
S-LOC 5 **	420/24 410 (500-½)	420/40 410 (500-¾)			
CIRCLING ***	500-1 486 (500-1)	540-1 526 (600-1)	540-1½ 526 (600-1½)	580-2 566 (600-2)	1020-3 1006(1100-3)

HIRL Rwy 5-23

Knots	60	90	120	150	180
Min:Sec	4:18	2:52	2:09	1:43	1:26

TAMPA, FLORIDA

Orig 31DEC20

27°51'N-82°31'W

MACDILL AFB (KMCF)

ILS or LOC RWY 5

SE-3, 31 DEC 2020 to 28 JAN 2021

SE-3, 31 DEC 2020 to 28 JAN 2021