

APP CRS

312°

Rwy Idg

4825

TDZE

82

Apt Elev

85

RNAV (GPS) Y RWY 31

SALINAS MUNI (SNS)

For inoperative MALSR, increase LNAV Cat D visibility to RVR 6000.
DME/DME RNP-0.3 NA. When local altimeter not received, use Monterey Rgnl altimeter setting and increase all MDA 60 feet and increase LNAV Cat C visibility to RVR 4000.

MALSR

MISSED APPROACH: Climb to 3000
direct MAFAF and left turn via track
267° to MARN and hold.

ATIS	NORCAL APP CON	SALINAS TOWER ★	GND CON	UNICOM
124.85	133.0 251.15	119.525 (CTAF) 239.3	121.7	122.95

ELEV 85

TDZE 82

HIRL Rwy 13-31

MIRL Rwy 8-26

REIL Rwy 13 and 26

3000

MAFAF

tr 267°

MARN

UGTAC

HEPIK 2.4 NM to UGTAC

IVUVY

WIGGL

312°

297°

3400

6000

0.5

2.4 NM

6.4 NM

9.1 NM

3000

MAFAF

MARN

UGTAC

HEPIK 2.4 NM to UGTAC

IVUVY

WIGGL

312°

297°

3400

6000

Procedure Turn NA

CATEGORY	A	B	C	D
LNAV MDA	440/24 358 (400-½)			440/50 358 (400-1)
CIRCLING	500-1 415 (500-1)	540-1 455 (500-1)	540-1½ 455 (500-1½)	760-2¼ 675 (700-2¼)

SALINAS, CALIFORNIA

Orig 27AUG09

36°40'N-121°36'W

RNAV (GPS) Y RWY 31

SALINAS MUNI (SNS)

SW-2, 31 DEC 2020 to 28 JAN 2021